

► **Overload Protectors**

Overload protectors are used to protect pressure gauges, pressure switches and other instruments from overpressure. If the pressure exceeds the maximum allowable value, an overload protector will bypass the instrument and return the pressure value to normal. Connections are available in 1/4" and 1/2" NPT M x F 1/4" NPT. Set points available from 50 psi to 6000 psi.



Part Number	NPT	Material
MP4-8/9	1/2"	316SS

► **Protective Rubber Boot**

Add a protective rubber boot to a 2.5" dial gauge, bottom or center back mount.



► **Maximum Registering Pointer Assembly (4")**

Add a Max Pointer Assembly to our GTG40XX Series Pressure Gauge. Minimum pressure range 0-200 psi/kPa. Liquid fillable.

