Accessories



Overload Protectors

Overload protectors are used to protect pressure gauges, pressure switches and other instruments from overpressure. If the pressure exceeds the maximum allowable value, an overload protector will bypass the instrument and return the pressure value to normal. Connections are available in 1/4" and 1/2" NPT M x F 1/4" NPT. Set point available from 29 psi to 870 psi.

Part Number	NPT	Material
MP4-8/9	1/2"	316SS



▶ Protective Rubber Boot

Add a protective rubber boot to a 2.5" dial gauge, bottom or center back mount.



▶ Maximum Registering Pointer Assembly (4")

Add a Max Pointer Assembly to our GTG40XX Series Pressure Gauge. Minimum pressure range 0-200 psi/kPa. Liquid fillable.

